



**I-10
BALDWIN COUNTY
CORE #1
EBOL
M.P. 35.4
12.0"
CRACK DEPTH 4.5"**



I-10
BALDWIN COUNTY
CORE #2
EBOL
M.P. 35.8
12.0"
CRACK DEPTH 3.0"



**I-10
BALDWIN COUNTY
CORE #3
EBOL
M.P. 36.2
13.0"
CRACK DEPTH 1.5"**



**I-10
BALDWIN COUNTY
CORE #4
EBOL
M.P. 36.8
13.25"
CRACK DEPTH 1.25"**



**I-10
BALDWIN COUNTY
CORE #5
EBOL
M.P. 37.4
13.5"**



**I-10
BALDWIN COUNTY
CORE #6
EBOL
M.P. 38.0
13.37"
CRACK DEPTH 1.0"**



**I-10
BALDWIN COUNTY
CORE #7
EBOL
M.P. 38.4
13.0"**



**I-10
BALDWIN COUNTY
CORE #8
EBOL
M.P. 38.8
12.5"
CRACK DEPTH 2.75"**



I-10
BALDWIN COUNTY
CORE #9
EBOL
M.P. 39.6
12.5"
CRACK DEPTH 1.5"



**I-10
BALDWIN COUNTY
CORE #10
EBOL
M.P. 40.0
13.25"
CRACK DEPTH 3.0"**



**I-10
BALDWIN COUNTY
CORE #11
EBOL
M.P. 40.6
13.25"
CRACK DEPTH 1.0"**



**I-10
BALDWIN COUNTY
CORE #12
EBOL
M.P. 41.2
14.0"
CRACK DEPTH 2.5"**



I-10
BALDWIN COUNTY
CORE #13
EBOL
M.P. 41.6
13.0"
CRACK DEPTH 3.0"



**I-10
BALDWIN COUNTY
CORE #14
EBOL
M.P. 42.0
13.5"
CRACK DEPTH 2.5"**



**I-10
BALDWIN COUNTY
CORE #15
EBOL
M.P. 42.4
12.5"
CRACK DEPTH 3.0"**




**I-10
BALDWIN COUNTY
CORE #16
EBOL
M.P. 42.8
14.5"
CRACK DEPTH 3.0"**



I-10
BALDWIN COUNTY
CORE #17
EBOL
M.P. 43.4
13.5"
CRACK DEPTH 3.0"



**I-10
BALDWIN COUNTY
CORE #18
EBOL
M.P. 43.8
14.25"**



**I-10
BALDWIN COUNTY
CORE #19
EBOL
M.P. 44.2
13.0"
CRACK DEPTH 3.5"**